

REPORT of SURVEY for REPAIRS.

No. 4230 Survey held at London Date June 12th 1880
 on the Bg Dimitson Master Wm Hojuss
 Tonnage 226 Built at Whitehaven When built 1826
 By whom built _____ Owners Hojuss & Co
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 4298 & 2989 Dated _____ Classed F.1
 Port London


Repairs *At the present time carried from the Captain the gunwale beams examined & a general overhaul*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Cupstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Trenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, *Is in a very efficient state both as regards the Hull & stores and I am of opinion is fit for the safe conveyance of my passengers & cargo as far from all parts of the State and may be classed F.1 with the Reserve*
 as required by the Instructions, *W. Middleton*

The Amount of Fee..... £ 1 : 1 : 0 is received by me, *W. Middleton*
 Committee Minute 15 June 1880
 Character assigned F.1



8050-209207