

REPORT of SURVEY for REPAIRS.

4267

No. 4267 Survey held at London Date June 13 1838
 on the Barck Hector Master Heenan
 Tonnage 293 Built at Bristol When built 1824
 By whom built _____ Owners Hanky & Co
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Dukeshore Dock

Original Survey, No. 1801, 2838 & 3568 Dated 1834 Classed *A.
 Port London

Repairs *at the present time a strike of sheathing shipped below the wales & the hooding for and supported & caulked - wales & upper works caulked and overhauled aloft - some few lower Deck Bolts shifted*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

Good *Good* *Good & Efficient*

General Observations and Opinion,
 as required by the Instructions,

*This ship is in my opinion entitled to remain as at present classed *A.*

George Bayley

The Amount of Fee.....£ 1 : 1 : - is received by me, *JH*

Committee Minute 3 July 1838

Character assigned *A *1st class - repairs*