

REPORT of SURVEY for REPAIRS.

No. 4314 Survey held at London Date June 30th 1837
 on the Ship Barretto Junior Master Saunders
 Tonnage 523 Built at Calcutta When built 1818
 By whom built _____ Owners Ridgely
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Pitchers Dry Dock

Original Survey, No. _____ Dated May 1835 Clasped A.E.
 Port London

Repairs. Wood ends listed and Caulked - Wales dubbed bright and caulked together with the Topside and Thrustams of the Deck - Stripped wood sheathing spiled, and renewed, and recoppered - generally overhauled aloft

The vessel presents a very firm appearance throughout

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treenails _____
 (Outside to the Water's Edge.)
 Rudder _____
 Windlass _____
 Capstan _____

Mast, Rigging & Sailing all overhauled

General Observations and Opinion, *This ship is throughout in good and efficient condition for the conveyance of dry and perishable cargoes to & from all parts of the world and should be*
Clasped A.E.
George Dayley

The Amount of Fee £ : : is received by me.

Committee Minute _____ 183 _____

Character assigned See annexed Survey