

REPORT of SURVEY for REPAIRS.

4329
 No. *1111* Survey held at *London* Date *Apr 13* 18*37*
 on the *W. Shepherdess* Master *Baker*
 Tonnage *295* Built at *Gundarland* When built *1833*
 By whom built _____ Owners *Laird & Co.*
 Port belonging to *Port Glasgow* Destined Voyage _____
 If Surveyed Afloat or in Dry Dock *Afloat*

Original Survey, No. _____ Dated _____ Classed _____
 Port _____

Repairs *1836 Stiffen Bulkhead & Loppings*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting <i>In good</i>	Wales <i>In good</i>	Masts, Yards, &c. <i>Sufficient</i>
Plank Shears <i>Condition</i>	Counter <i>Condition</i>	Sails <i>8 good</i>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

*She appears throughout a very fair built
 vessel and well fastened. The Master
 states her to be built wholly of English & American oak
 except the Hog Keelson &c. She is entitled to 10 A1-*

The Amount of Fee.....£ : : is received by me,

Committee Minute _____ 18 _____

Character assigned _____