

REPORT of SURVEY for REPAIRS.

4329

No. 4329 Survey held at Londou Date July 13 1838
 on the Barb Shepherds Master Biggan
 Tonnage 295 Built at Sunderland When built 1833
 By whom built L. Brown Owners Said Ho
 Port belonging to Glasgow Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock Pitcher Dock

Original Survey, No. 3 Dated 1834 Classed GA
 Port Glasgow

Repairs At the present time shipped. Caulked throughout
 Upper Course wood sheathed Felled and Capped upon
 paper to the Wale - 2 pair of Iron Hanging knees to
 the Quarter Deck Beams. It's some Iron Hanging knees
 new put in Last Voyage.

The Surveyor is also required to state the present Condition of the

| Decks | Transoms | Windlass |
|-------------------------------|--|-----------------------------|
| Upper Deck Beams & Fastenings | Timbers of the Frame | Capstan |
| Lower Deck Beams & Fastenings | Topsides | Pumps |
| Spirketting | Wales | Masts, Yards, &c. |
| Plank Shears | Counter | Sails |
| Waterways | Plank & Treenails (Outside to the Water's Edge) | Cables |
| Hatchway Comings | Rudder | Anchors No. of <u>3.1.1</u> |
| Breasthooks | Copper <u>1838</u> | Standing & Running Rigging |

Good }
 Good }

Good and efficient }

General Observations and Opinion,
 as required by the Instructions,

This ship has a very favorable appearance
 throughout and it is my opinion entitled
 to be continued as at present classed GA!

George Bayley

The Amount of Fee.....£ 1 : 1 : - is received by me, HA

Committee Minute 24 July 1838

Character assigned GA 1 under repairs

