


4402



Repairs

The Surveyor is also required to state the present Condition of the

*General Observations and Opinion,
as required by the Instructions,*

General Observations and Opinion,
as required by the Instructions, She is now very firm & substantiated in her upper
works the sheer strokes & plank sheers being new of oak
A considerable part of the deck still appears to be shifted
The ceiling below the hold beams is in an indifferent
state, the inner post is also deflected She appears to be nearly
ready for service.

The Amount of Fee.....£ 1 : 1 : - is received by me, *Wm. Smith of Lorch and*

Committee Minute 28 Aug 18

Character assigned

C. F. SEYFANG, PRINTER, FARRINGDON STREET, LONDON.

CON603-0193

favorable

Lloyds Register
Foundation