

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 4408 Survey held at London Date August 20th 1830
 on the Bk Savinia Master J. Hall
 Tonnage 301 Built at New Brunswick When built 1826
 By whom built _____ Owners H. R. P. P. P.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 318, 1210, 1961 Dated May 10 30 & 2 288 Classed A. 1
 Port Liverpool

Repairs At the present time decks & wales caulked

Is deficient a Bower Anchor & Stream Hawser of which due notice has been given

Aug 23 The above has been supplied
 The Surveyor is also required to state the present Condition of the WM

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkelting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of <u>2 Bowers 1 Stem 2 Kedge</u>
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, Is in very good condition and having been repaired according to the
 as required by the Instructions, rules at Liverpool may remain in her present shape
when the spare Bower Anchor & Hawser has been put
on board.

The Amount of Fee.....£ 2 : 2 : is received by me, WM

Committee Minute 24 Aug 18

Character assigned A. 1