

REPORT of SURVEY for REPAIRS.

No. 4424 Survey held at London Date 25 Aug 1838  
on the "John Adams" late Master Barton  
Marchioness of Londonderry  
Tonnage 417 Built at Sunderland When built 1838  
By whom built Giles Owners Burton  
Port belonging to London Destined Voyage West Indies Jamaica  
If Surveyed Afloat or in Dry Dock Hutchins Dock

Original Survey, No. 976 Dated \_\_\_\_\_ Classed 11 A1  
Port Sunderland

Repairs

At the present time bottom caulked, the upper  
course sheathed with wood, & the ship coppered on  
paper, nearly to the wales.

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,  
as required by the Instructions,

She is a well built ship and in my opinion  
entitled to her present class -

The Amount of Fee.....£ 2: 2: - is received by me, JA

Committee Minute 31 Aug 1838

Character assigned 11 A1 repaired & coppered  
repairs