

REPORT of SURVEY for REPAIRS.

4430

No. 4430 Survey held at London Date 27 Aug 1838
 on the Ship Washburn Master _____
 Tonnage 523 Built at Calcutta When built 1817
 By whom built _____ Owners Hyde & Sons
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Gordons Dock

Original Survey, No. 7781911 Dated _____ Classed F.1
 Port London

Repairs

At the present time stepped, double long caulked, and reoppered to the keels, new Rudder, and generally overhauled.

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frams	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors
Breasthooks	Copper	Standing & Running Rigging

Hyde & Sons
Condition
Good
New
2
24 fms C & 11 fms W
3 B 1 & 1 K
good

General Observations and Opinion, as required by the Instructions,
*The vessel doubled from the keel up over the keels in 1833. Is everywhere sound and substantial fastenings firm, fit for the conveyance of any and perishable cargoes to and from all parts of the world, and in my opinion should be classed * F.1*

The Amount of Fee.....£ 1 : 1 : is received by me, *H. J. Courtenay*
 Committee Minute 30 Aug 1838
 Character assigned F.1

LON603-0270



Hyde & Sons