

# ANNUAL SURVEYS.

4487

No. 4487 Survey held at London Date Sept. 13<sup>th</sup> 1830  
 on the Bk. William Bryan Master J. Roman  
 Tonnage 312 Built at Southampton When built 1816  
 By whom built \_\_\_\_\_ Owners Demott & Co  
 Port belonging to London Destined Voyage South Australia  
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 7034 2415 Port of London 1036 Classed A 1

The Surveyor is required to state the present Condition of the

|                               |   |                            |
|-------------------------------|---|----------------------------|
| Decks                         | Breasthooks   | Capstan                    |
| Upper Deck Beams & Fastenings | Transoms  | Pumps                      |
| Lower Deck Beams & Fastenings | Timbers of the Frame                                  | Masts, Yards, &c.          |
| Spirketting                   | Topsides  | Sails                      |
| Plank Shears                  | Wales   | Cables                     |
| Waterways                     | Plank and Treenails<br>(Outside to the Water's Edge.) | Anchors No. of             |
| Hatchway Comings              | Rudder  | Standing & Running Rigging |
|                               | Windlass  | Copper                     |

General Observations and Opinion, At the present time the new deck beam under the keel of the  
 as required by the Instructions, bowsprit which was sprung and the upper works caulked;  
The appearance of this vessel is extremely favorable no  
symptoms of weakness or decay, and is altogether in a very  
efficient state and from her large repairs I recommend her  
 Committee Minute 10<sup>th</sup> Sept 1830 conveyance of dry & perishable cargoes to &  
 Character assigned A 1 from all parts of the world

No. 381 Survey held at London Date Sept. 17<sup>th</sup> 1830  
 on the Lt Frederick Wilhelm Master Veltz  
 Tonnage 229 Built at Wekermunde When built 1832  
 By whom built \_\_\_\_\_ Owners Veltz  
 Port belonging to Wekermunde Destined Voyage Stettin  
 If Surveyed Afloat or in Dry Dock in the Katherine Dock

Original Survey, No. 947 2482 Port of Liverpool London Classed 7A 2

The Surveyor is required to state the present Condition of the

|                               |   |                            |
|-------------------------------|---|----------------------------|
| Decks                         | Breasthooks   | Capstan                    |
| Upper Deck Beams & Fastenings | Transoms  | Pumps                      |
| Lower Deck Beams & Fastenings | Timbers of the Frame                                  | Masts, Yards, &c.          |
| Spirketting                   | Topsides  | Sails                      |
| Plank Shears                  | Wales   | Cables                     |
| Waterways                     | Plank and Treenails<br>(Outside to the Water's Edge.) | Anchors No. of             |
| Hatchway Comings              | Rudder  | Standing & Running Rigging |
|                               | Windlass  | Copper                     |

General Observations and Opinion, I in a very efficient state and well found with anchors  
 as required by the Instructions, Cables, Harpers and stores, I am of opinion may now  
be raised to 7A 1

Committee Minute 10<sup>th</sup> Sept 1830

Character assigned 7A 1



© 2019

Lloyd's Register  
Foundation