

REPORT of SURVEY for REPAIRS.

No. 4508 Survey held at London Date Sept. 26th 1830
 on the By Jordonson Master Jordonson
 Tonnage 200 Built at Shields When built 1829
 By whom built _____ Owners Jordonson
 Port belonging to Newcastle Destined Voyage Harbysport
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 530, 2116, 3818 & 4115 Dated 1830 Classed Continued A 13 Years
 Port of London

Repairs At Dantzic in August last had new Decks and the
Sodging Knives of the Hold Beams re-bolted

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Well</u>
Plank Shears	Counter	Sails <u>Good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	<u>Copper</u>	Standing & Running Rigging

General Observations and Opinion, Is in a very efficient state both as regard the
 as required by the Instructions, hull & stores and I am of opinion well entitled
to her present Class

The Amount of Fee.....£ 1 : 1 : 0 is received by me, Wm Jordonson paid into the Office

Committee Minute 28 Sept 1830

Character assigned 3 A 1 Good repairs