

# REPORT of SURVEY for REPAIRS.

No. 4509 Survey held at London Date July May 18 38  
on the Petch Lady Susan Master Henry  
Tonnage 1890 Built at Wartmouth When built 1813  
By whom built 1565 Owners Henry  
Port belonging to London Destined Voyage Atlantic  
If Surveyed Afloat or in Dry Dock New Beam Dock

Original Survey, No. \_\_\_\_\_ Dated \_\_\_\_\_ Classed \_\_\_\_\_  
Port \_\_\_\_\_

**Repairs** At the present time in consequence of damage  
9 new first futtocks, Chocks of other futtocks on the  
Starboard side refixed, three new Deck beams some new  
Knees, great many new turnbills, caulking from the keel  
up over all. New ceiling including bily strokes on the  
Starboard side from the keelson to the hold beams.  
2 new Hold Beams or Hombro a short time since

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>Sheathed &amp; fitted 1838</u>	Standing & Running Rigging

General Observations and Opinion, *In opening this vessel to repair the damage*  
as required by the Instructions, *the frame thereby exposed proved very sound and*  
*good & she is now in an efficient condition fit*  
*for the conveyance of any perishable cargo & may*  
*be safely sailed.*

The Amount of Fee.....£ : : is received by me,

Committee Minute \_\_\_\_\_ 18

Character assigned See annexed Survey