

REPORT of SURVEY for REPAIRS.

No. _____ Port of London Date July 16th 1835
Survey of the Bark Gratitude Master M. Todd
Tonnage 271 By whom built _____ Where built Yarmouth
When built 1833 Owners Lidgett & Co Port belonging to London
Destined Voyage New York
Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. _____ Dated February 1834
Port London

Repairs. Bottom and wales caulked & recoppered

General Observations
and Opinion, as
required by the
Instructions.

} Bottom and wales shifted 2 between with 5 feet shift
generally in a few instances shorter - The average would be
more than 5 feet.
3. Strakes at the Floor Head outside 4 inches thick and 2 of 3 1/2
upward course of iron Oak Plank.
Hull and materials are in good order & condition.

George Dingley

The Amount of Fee..... £ 1 : 1 : - is received by me. MA
24/10/38

Committee Minute _____ 183

Character assigned See annexed Survey

For the Survey



© 2019

Lloyd's Register
Foundation

LON603-0310