

4589

# REPORT of SURVEY for REPAIRS.

*[Handwritten signature]*

No. 4589 Survey held at London Date Sept 15 1838  
on the Ship David Lyon Master Selby  
Tonnage 47 1/2 Built at Ipswich When built 1819  
By whom built Lacey Bayley Owners Selby & Co Sydney  
Port belonging to London Destined Voyage Sumatra  
If Surveyed Afloat or in Dry Dock Blackwall

Original Survey, No. 6638395 Dated 1834/1837 Classed 1834 restored 4 years A1  
Port London

**Repairs** *at the present time, the remaining part of the  
Wales shifted together with some planks under the  
Quarter and the wing transom. Caulked aloft*

*The timbers of this ship were quite sound and good  
& the planks taken out were <sup>generally</sup> sound and good  
inside -*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, *In my opinion this ship is well entitled*  
as required by the Instructions, *to remain as classed A1*  
*George Bayley*

The Amount of Fee.....£ 2 : 2 : - is received by me, *[Signature]*

Committee Minute 30th Oct. 1838

Character assigned continued Restored 1834 7 years  
*[Signature]* Record Repairs