

REPORT of SURVEY for REPAIRS.

4726

No. 4726 Survey held at London Date 15 Oct 1838
 on the Ship Thomas Coutts Master Warren or Werner
 Tonnage 1365 Built at London When built 1814
 By whom built _____ Owners Majoribanks
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1044 Dated 1834 Classed FI
 Port London

Repairs

Stations to have been Sheathed and Coppered
at Ship Gordon 1836 have not been at sea since
now Coulthard from the Copper at See annexed Survey

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treencails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

Sum of opinion
this Ship is fit for
the service and of any
and from all parts of it
the work may be carried on

The deck is a little sagged near the main
mast in other parts the opinion is good
for condition, fastenings are all firm
is fit for the service of any and possible
cargoes & may be continued as shipped

The Amount of Fee £ 3 : 3 : - is received by me, H. P. Muntz

Committee Minute 11 Decr 1838

Character assigned

B. & Record Copper



© 2019

Lloyd's Register
 Foundation
 LON604-0061