

REPORT of SURVEY for REPAIRS.

No. 4745 Survey held at London Date 4 Oct to 9 Dec 1838
 on the St Sophia Master Barclay
 Tonnage 376 Built at Chips town When built 1822
 By whom built — Owners Genl
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock —

Original Survey, No. 7108.3762 Dated — Classed *A.1
 Port London

Repairs

At the present time at my suggestion and under my inspection
 new solid waterways stroke of black next theuto part new
 black sheers & shear strokes, plank in topside in way of chain
 bolts some pieces in topsides, new Stations, the greater part
 of main black shifted in the west end, little more to shift
 between the Hatchways, topsides waterways caulked,
 the two pointers put in, 12 new upper deck knees.
 two new knees to ~~the~~ the forward beam of quarter
 deck and new break

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Sheers	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

The ends of the upper deck beams and the heads
 of the top timbers exposed in the repairs were
 found to be very good, is now in an efficient state in
 hull and equipment, fit for the conveyance of dry and perishable
 cargo to & from all parts of the world, and may be continued

The Amount of Fee.....£ 2 : 2 : — is received by me, Wm Barclay

Committee Minute 18 Dec^r 1838

Character assigned A.1