

REPORT of SURVEY for REPAIRS.

No. 4750 Survey held at London Date Oct 10th 1836
on the Ship Thomas Coutts Master Christie
Tonnage 1365 Built at London When built 1817
By whom built _____ Owners Majoribanks
Port belonging to London Destined Voyage China
If Surveyed Afloat or in Dry Dock At Barnard's Dry Dock

Original Survey, No. _____ Dated 1834 (April 4th)
Port London

Repairs.

At the present time stripped caulked from the keel
over all & recooped Main mast out - put
new false keelson - thoroughly overhauled inside
& out. Refitting Rigging &c. &c. Dock
Ship hung & keel & stem caulked

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
Spirketting _____
Plank Shears _____
Topsides _____
Upper Deck with its Appendages _____
Lower Deck Fastenings _____

Wales _____
Counter _____
Plank and Treenails _____
(Outside to the Water's Edge.)
Rudder _____
Windlass _____
Capstan Refitted

General Observations and Opinion,
as required by the Instructions,

This ship has caulked well and presents a
very firm appearance throughout she is in
my opinion eligible to her present class
George Bayley

The Amount of Fee.....£ : : is received by me.

Committee Minute _____ 183 _____

Character assigned _____