

REPORT of SURVEY for REPAIRS.

4783

No. 4783 Survey held at London Date December 26 1838
 on the Brig Sisters Master Ramsay
 Tonnage 260 Built at Auld When built 1818
 By whom built _____ Owners Fryer & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock M^r Kitchies Dry Dock

Original Survey, No. 575, 1646 Dated April 1838 Classed A. 1
 Port London

Repairs

at the present time, Woodheating stripped off upper & main bottom pulked thence up - and overhauled aloft - upper course Woodheating on Lells & Stakes -

Up Dabium fastenings new 1836
 L & B beam Lee - new 1833

The Surveyor is also required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Windlass _____
Upper Deck Beams & Fastenings <u>4</u>	Timbers of the Frame <u>4</u>	Capstan _____
Lower Deck Beams & Fastenings <u>4</u>	Topsides <u>4</u>	Pumps _____
Spirkettling <u>4</u>	Wales <u>4</u>	Masts, Yards, &c. <u>Overhauled</u>
Plank Shears <u>4</u>	Counter <u>4</u>	Sails <u>good efficient</u>
Waterways <u>4</u>	Plank and Treenails <u>4</u> (Outside to the Water's Edge)	Cables _____
Hatchway Comings <u>4</u>	Rudder <u>4</u>	Anchors No. of _____
Breasthooks <u>4</u>	Copper <u>up</u>	Standing & Running Rigging _____

General Observations and Opinion,
 as required by the Instructions,

In my opinion this vessel is eligible to remain
 as classed A. 1
George Bayley

The Amount of Fee.....£ 1 : 1 : - is received by me,

Committee Minute 4 Jan 3 1839

Character assigned A. 1 second repairs