

4805

Change of Registry
REPORT of SURVEY for REPAIRS.

No. 4805 Survey held at Londre Date 25th 18 39
on the M. Frederick Master Wm. Wales
Tonnage 281 Built at Bristol When built _____
By whom built _____ Owners Wm. Smith London 110
Port belonging to Londre Destined Voyage Alexandria
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 2148, 2163 & 3052 Dated Dec^r 1836 . Classed E.A.
Port Londre

Repairs.

see former report

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
Spirketting _____
Plank Shears _____
Topsides _____
Upper Deck with its Appendages _____
Lower Deck Fastenings _____

Wales _____
Counter _____
Plank and Treenails _____
(Outside to the Water's Edge)
Rudder _____
Windlass _____
Capstan _____

General Observations and Opinion,
as required by the Instructions,

*The owners & Master has been charged
since last report*
Continued

The Amount of Fee..... £ 1 : 1 : — is received by me. *Wm. Wales*
25/12/39

Committee Minute 11 Jan 1839

Character assigned

Record Change of Owners & Master