

REPORT of SURVEY for REPAIRS.

& Charge of Owners

No. _____ Survey held at London Date Dec^r 5th 1830
on the By Whysse Master H. C. Riley
Tonnage 100 Built at Yarmouth When built 1829
By whom built Piston Owners Chadwick
Port belonging to _____ Destined Voyage Cadiz
If Surveyed Afloat or in Dry Dock in the Dry Dock

Original Survey, No. _____ Dated 1834 Classed 12 A 1

Port of Greenock

Repairs Bottom Caulked & Popped over paper

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Well</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>Sound</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, Is in a very efficient state both as regards the Hull
as required by the Instructions, & Stowage and may retain her present Class

W. Middleton

The Amount of Fee.....£ : : is received by me,

Committee Minute _____ 18 _____

Character assigned _____