

REPORT of SURVEY for REPAIRS.

No. 4858 Survey held at London Date March 8 1837
 on the Brig Sarah Master Rogers
 Tonnage 201 Built at Newcastle When built 1825
 By whom built _____ Owners J. G. & Co. - Smith
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock On the voyage

Original Survey, No. 1740 Dated _____ Classed 10 A now B
 Port London

Repairs. At the present time in consequence of having been
 ashore - Stripped caulked throughout - several treenails
 shifted - Three shakers at each side were taken
 up to examine the timbers which are found
 to be uninjured and are well squared & in good
 condition.

All the damages are efficiently repaired - now
 single bottom -

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treenails _____
 (Outside to the Water's Edge.) _____
 Rudder _____
 Windlass _____
 Capstan _____

Masts, Sails Rigging, Cable & Anchors in good condition

General Observations and Opinion, This vessel has a very favorable appearance
 as required by the Instructions, throughout & is in my opinion entitled to be
 classed A.1

George Bayley

The Amount of Fee.....£..... is received by me. not Paid

Committee Minute 25 June 1837

Character assigned A.1