

REPORT of SURVEY for REPAIRS.

Change of Owners

4894

No. 1 Survey held at London Date Feb 10 1839
 on the Ship Abbeyston Master J. Cull
 Tonnage 457 Built at Spawick When built 1819
 By whom built _____ Owners Godwin & Lee
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 282, 1071 & 3812 Dated 1835 Classed Registered O.A.I
 Port of London

Repairs In good condition

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Water</u>
Plank Shears	Counter	Sails <u>Grand</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, In a very efficient state and may continue
 as required by the Instructions, in her present shape

W. Middleton

The Amount of Fee.....£ 2 : 2 : - is received by me, HA

Committee Minute 12 Feb 1839

Character assigned Registered O.A.I

