

4907

Change of property

REPORT of SURVEY for REPAIRS.

No. 393 Survey held at London Date Decr 26 1838
 on the Gk Fulmar Master _____
 Tonnage 193 Built at New Brunswick When built 1833 Aug
 By whom built _____ Owners Rosier 2
 Port belonging to London Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock Mountain Dock ways

Original Survey, No. 184182/81 Dated 1836 Classed 4 A 1 A.1
 Port London

Repairs *at the present time the bottom beamed - the copper appears to have been stripped off some time since.*

*Mem - Circular sent Decr 31. See 63 - no answer
 yet received - G.B.*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

Good *Good* *Good & efficient*

General Observations and Opinion,
 as required by the Instructions,

The appearance of this report is favorable,
George Bayley

The Amount of Fee.....£ : : is received by me,

Committee Minute 15 Feb 1839

Character assigned Expense Character not opened