

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date October 7 1839
 on the St Prince of Serre Otago Master J. Ladd
 Tonnage 126 Built at Ramsgate When built 1819
 By whom built _____ Owners Rahm, & Co
 Port belonging to London Destined Voyage Rotterdam
 If Surveyed Afloat or in Dry Dock on the Ways

Original Survey, No. _____ Dated Jan^y 10 39 Classed A. 1
 Port London

Repairs *At the present time new Paving Board & Waterways
 Planking refitted down, keelnails examined & caulked*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Corra	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

*In good condition for the safe conveyance
 of dry & perishable cargoes & may continue
 as before*

W. H. H. H. H.

The Amount of Fee.....£ : : is received by me,

Committee's Minute _____ 18 _____

Character assigned _____