

ANNUAL SURVEYS.

4935

No. 450 Survey held at LONDON Date Feb 18 1839
 on the Ship Henderson Master Lamb
 Tonnage 424 Built at Whitby When built 1819
 By whom built _____ Owners Richardson
 Port belonging to Whitby Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 11 Port of Whitby Anterior 1834 Classed A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

Good *Good* *Good & efficient*

General Observations and Opinion, *In my opinion this vessel is eligible to remain as at present classed A1*

Committee Minute 22 Feb 1839

Character assigned A1

No. 180 Survey held at LONDON Date Feb 4/18 1839
 on the Boat Egyptian Master Duncan
 Tonnage 355 Built at St Shields When built 1825
 By whom built _____ Owners Lewick & Co
 Port belonging to Newcastle Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Lincoln Dock

Original Survey, No. 403, 2127 & 3070 Port of LONDON May 1838 Classed *F.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

Good *Good* *Good & efficient*

General Observations and Opinion, *This vessel presents a favorable appearance throughout & in my opinion this entitles to remain as classed *F.1*

Committee Minute 22 Feb 1839

Character assigned F.1