

ANNUAL SURVEYS.

4940

No. 1152 Survey held at London Date Feb 18 1838
 on the Brig Harriot Master John M. Cabe
 Tonnage 205 1/2 Built at Sunderland When built 1838
 By whom built Rezley Owners John R. Todd & Co. Register
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Evans Dock

Original Survey, No. 1152 Port of Sunderland Nov 2 1838 Classed 8A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,
 I have examined the ceiling planks which appear to be
 second-hand English oak - and some of the new plank in the
 bridge is of moderate quality - I have suggested the propriety
 of removing the objectionable planks - even then there will
 in my opinion be but barely eligible to 8A1

Committee Minute

Character assigned

8A1

22 Feb 1839

George Bayley

No. 1153 Survey held at London Date Feb 19 1839
 on the Brig Sumatra Master Richard
 Tonnage 183 Built at Poole When built 1834
 By whom built _____ Owners Richard
 Port belonging to London Destined Voyage St Jago de Cuba
 If Surveyed Afloat or in Dry Dock Gun Dock ways

Original Survey, No. 1153 Port of Liverpool 1837 Classed 11A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>good</u>

General Observations and Opinion,
 as required by the Instructions,
 The copper having been rubbed off in Gloucester
 Canal - this is in good condition in my opinion
 is entitled to be present Class 11A1

Committee Minute

Character assigned

11A1

22 Feb 1839

George Bayley