

REPORT of SURVEY for REPAIRS.

4970

No. 447 Survey held at London Date February 23 1834
 on the SS Two Sisters Master D. Thomas
 Tonnage 124 Built at Littlehampton When built 1810
 By whom built _____ Owners Williams
 Port belonging to London Destined Voyage Dublin
 If Surveyed Afloat or in Dry Dock in the Ways

Original Survey, No. 3482562 Dated _____ Classed A. 1
 Port London

Repairs At the present time Copper stripped off, new Covering
boards, part new Sheer strake & waterway & Spirketting
Caulked and a general overhaul

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings <u>Good</u>	Topsides	Pumps
Spirketting <u>of the</u>	Wales	Masts, Yards, &c. <u>Still</u>
Plank Sheers <u>Good</u>	Counter <u>Good</u>	Sails <u>found</u>
Waterways <u>fixed</u>	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	<u>Copper</u>	Standing & Running Rigging

General Observations and Opinion, The timbers where she has been opened are very
 as required by the Instructions, sound & good, no appearance of decay or weakness
and Sam. of opinion is fit for the safe conveyance
of dry & perishable cargoes & may retain her
present Class A. 1 W. Williams

The Amount of Fee.....£ 2 : 10 : 6 is received by me, AD

Committee Minute 5 March 1834

Character assigned A. 1 sound repair

