

ANNUAL SURVEYS.

5088

No. 438 Survey held at London Date Mar 23 1839
 on the Ship Prince of Wales Master Royal
 Tonnage 351 Built at London When built 1773
 By whom built _____ Owners H.B.L.
 Port belonging to London Destined Voyage H.B.L.
 If Surveyed Afloat or in Dry Dock Blackwall Dock

Original Survey, No. 1294, 2302, 3237 & 3096 Port of London

1839 Classed F.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

Good *Good* *Overhauling*
good sufficient

General Observations and Opinion, *At the present time removing several planks*
of the doubling in consequence of timber being
cut with the ice - the ice blocks taken off & hauled up on
generally overhauled - in my
opinion this is for the convenience
 Committee Minute 2 April 1839
 Character assigned F.1 *of dry and suitable cargoes to be*
from all parts of the hold & should be
Classed F.1 *George Bayley*

No. _____ Survey held at London Date Mar 23 1839
 on the Brig Ruby Master _____
 Tonnage 44 Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock London Docks

Original Survey, No. _____ Port of _____

Classed _____

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

Good *Good* *Good & efficient*

General Observations and Opinion, *At the present time Copper examined and*
is in good condition throughout

Committee Minute _____ 1839

Character assigned _____

George Bayley

6 Annals
1 First Entry
6. Repairs

13



© 2019

Lloyd's Register
Foundation