

ANNUAL SURVEYS.

5105

No. 501 Survey held at London Date April 4 1839
 on the Brig Bruce Castle Master Murray
 Tonnage 169 Built at Clyde When built 1829
 By whom built _____ Owners H. Kerr
 Port belonging to London Destined Voyage For sale
 If Surveyed Afloat or in Dry Dock St Katharine's Dock

Original Survey, No. 1253, 20418 Port of London 1835 Classed A. 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Sound</u>	Capstan
Upper Deck Beams & Fastenings <u>Fair</u>	Transoms	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Sound</u>	Masts, Yards, &c.
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, The Nelson, Bidge Planks & Ceiling is very much
 as required by the Instructions, decayed and works at the Hold Beams, I am of opinion
After left this in her present state she is not fit for the safe
day in working conveyance of dry & perishable cargoes
W. B.

Committee Minute

Character assigned See Survey No 5260

Wm. L. Smith & W. Middleton
W. B. 5th April

No. 541 Survey held at London Date April 4 1839
 on the Brig Emily Master T. R. R. R.
 Tonnage 100 Built at Sunderland When built 1832
 By whom built _____ Owners R. R. R. R.
 Port belonging to London Destined Voyage Hambro's
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1253, 20418 Port of London 1834 Classed A. 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks	Capstan <u>Good</u>
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides <u>Good</u>	Sails <u>Well found</u>
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging <u>Good</u>
	Windlass	Copper

General Observations and Opinion, Cautioned in 1830 and is at the present time in a
 as required by the Instructions, very efficient state both in the Hull & stores
and may continue as Clased

Committee Minute

Character assigned

W. B. 5th April 1839
W. B. 5th April
 © 2019
 Lloyd's Register
 Foundation