

REPORT of SURVEY for REPAIRS.

No. 64 Survey held at London Date 1 April 18 39
 on the St. Averino Master Warming
 Tonnage 463 Built at Cebu When built 1828
 By whom built — Owners St. and
 Port belonging to London Destined Voyage —
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 3470 Dated — Classed St. A.
 Port London

Repairs At the present time shipped & sheathed with yellow pine to the hulls

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

Good Condition *Good Condition* *Sufficient and Good*

General Observations and Opinion,
 as required by the Instructions

The appears throughout in good condition and fit for the voyage once any & possible repairs be made and from all parts of the world and may be continued as above

The Amount of Fee.....£ 1 : 1 : — is received by me, St. and

Committee Minute 9 April 1839

Character assigned St. and