

ANNUAL SURVEYS.

5120

No. 520 Survey held at London Date April 8th 1839
 on the Bk Hope Master J Smith
 Tonnage 346 Built at Prince Edward Island When built 1820
 By whom built _____ Owners Pentagon
 Port belonging to Sunderland Destined Voyage North America
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 838, 1588 Port of Liverpool Clapnet £2 No. 31 Classed V, 2

The Surveyor is required to state the present Condition of the

Decks <u>Indifferent</u>	Breasthooks <u>Good</u>	Capstan _____
Upper Deck Beams & Fastenings <u>Indifferent</u>	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirketting <u>Indifferent</u>	Topsides <u>Indifferent</u>	Sails _____
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank and Treenails (Outside to the Water's Edge.) _____	Anchors No. of <u>2 Bowers</u>
Hatchway Comings <u>Good</u>	Rudder <u>Good</u>	Standing & Running Rigging <u>Good</u>
	Windlass _____	Copper _____

General Observations and Opinion, This vessel works very considerably more particularly so
 as required by the Instructions, at the H.D. Broom, the Sprits Decayed; also Stripped
her in the Dry Dock Oct 8. 1830; the Hull is worn eating and her
general appearance a together very indifferent, I am of opinion she
is not entitled to her present Class

Committee Minute Report of April 183 Write to Owners
 Character assigned Reduced to F2 all Whitton
U U U

No. 157 Survey held at London Date April 8th 1839
 on the Bk Georgetown Master Thorne
 Tonnage 412 Built at Isle of Man When built 1836
 By whom built _____ Owners Adams
 Port belonging to Glasgow Destined Voyage Dumfries
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 3002 Port of London 1836 Classed 7A1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirketting <u>Good</u>	Topsides _____	Sails <u>Good</u>
Plank Shears _____	Wales <u>Good</u>	Cables <u>Sufficient</u>
Waterways _____	Plank and Treenails (Outside to the Water's Edge.) _____	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion, Is in very good condition both in the Hull & Stores & may
 as required by the Instructions, continue as Classed

Committee Minute Report of April 183
 Character assigned 7A1 all Whitton
U U U



© 2019

Lloyd's Register
Foundation

7540-0497