

# ANNUAL SURVEYS.

3135

No. 105 Survey held at Lidon Date April 11<sup>th</sup> 1839  
 on the Brig Harmony Master W. Taylor  
 Tonnage 231 Built at Yarmouth When built 1837  
 By whom built \_\_\_\_\_ Owners Leake  
 Port belonging to Lidon Destined Voyage Subador  
 If Surveyed Afloat or in Dry Dock in the Ways

Original Survey, No. 1141, 2439 Port of Lidon 1836 Classed 11A1  
2560

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings <u>"</u>	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Spirkettling <u>"</u>	Topsides <u>"</u>	Sails <u>"</u>
Plank Shears <u>"</u>	Wales <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge)	Anchors No. of <u>Well found</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging <u>"</u>
	Windlass _____	Copper _____

General Observations and Opinion,  
 as required by the Instructions,

At the present time caulked and is in a very  
 high state of efficiency and may continue  
 in her present shape

Committee Minute 16 April 1839

Character assigned 11A1

No. 238 Survey held at Lidon Date April 11<sup>th</sup> 1839  
 on the St Richard Mount Master Longridge  
 Tonnage 170 Built at Shorcham When built 1834  
 By whom built \_\_\_\_\_ Owners G. Walker  
 Port belonging to Lidon Destined Voyage Cape of Good Hope  
 If Surveyed Afloat or in Dry Dock in the Ways

Original Survey, No. 1 Port of Shorcham 1834 Classed 11A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings <u>"</u>	Transoms _____	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame _____	Masts, Yards, &c. <u>"</u>
Spirkettling <u>"</u>	Topsides _____	Sails <u>Well found</u>
Plank Shears <u>"</u>	Wales <u>Good</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank & Treenails <u>"</u> (Outside to the Water's Edge)	Anchors No. of <u>"</u>
Hatchway Comings <u>"</u>	Rudder _____	Standing & Running Rigging <u>Good</u>
	Windlass _____	Copper <u>1837</u> <u>See note 4<sup>pe</sup></u>

General Observations and Opinion,  
 as required by the Instructions,

Very good condition and may retain  
 her present shape

Committee Minute 16 April 1839

Character assigned 11A1



© 2019

Lloyd's Register  
 Foundation

Lon604-0512