

REPORT of SURVEY for REPAIRS.

No. 87 Survey held at London Date April 13th 1839
 on the S^r Rebel Master Springer
 Tonnage 130 Built at Yarmouth When built 1833
 By whom built _____ Owners Ogilby & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in Fountain Dock

Original Survey, No. 325 Dated 1836 Classed 12 A 1
 Port of London

Repairs Copper stripped off, caulked & reshipped over
 Paper to the 4th feet mark

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>Good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables <u>Sufficient</u>
Hatchway Comings	Rudder	Anchors No. of _____
Breasthooks	Copper	Standing & Running Rigging _____

General Observations and Opinion, In a very efficient state both in the Hull &
 as required by the Instructions, Stoves and may continue as before

Special L. 1. 1. 0

[Signature]

The Amount of Fee.....£ 10 : 6 is received by me, *[Signature]*

Committee Minute 19 April 1839

Character assigned 12 A 1 reshipped Copper