

REPORT of SURVEY for REPAIRS.

No. 384 Survey held at Sunder Date April 5th 1839
on the Schooner Wizard Master J. Ward
Tonnage 101 Built at Haverhoe When built 1831
By whom built 56 Owners H. Linn
Port belonging to Sunder Destined Voyage _____
If Surveyed Afloat or in Dry Dock on the Ways

Original Survey, No. 2582 Dated 1836 Classed 10 A 1
Port of Sunder

Repairs *At the present time in consequence of damage has had seven new Stantims, part new Rails & Butwark new Gallies Bitts two planks shifted in the Decks & Caulked from the Copper upwards*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, *Is in very good condition and may continue as required by the Instructions, no Repair*

W. H. Doleman

The Amount of Fee.....£ 10 : 6 is received by me, *H*

Committee Minute 16 April 1839

Character assigned 10 A 1 *under Dan. Repair*

Rec'd 2. 2. 0