

REPORT of SURVEY for REPAIRS.

5159
 No. 5159 Survey held at London Date March 1837
 on the Scho Charles Carter Master Cristal
 Tonnage 175 Built at Gouham When built 1833
 By whom built M Bask Owners J Cristal
 Port belonging to London Destined Voyage Manila
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. _____ Dated 1835 August 11 At
 Port London

Repairs. At the present time stripped bottom caulked
and reopined

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appenlages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treenails _____
 (Outside to the Water's Edge.)
 Rudder _____
 Winlass _____
 Capstan _____

General Observations and Opinion,
 as required by the Instructions,

This vessel contains no sound and fastenings
are found. My opinion is continued as
above
Hamilton

The Amount of Fee.....£ : : is received by me.

Committee Minute _____ 183 _____

Character assigned _____