

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date March 29 1834
 on the Schooner Charles Carter Master Christate
 Tonnage 175 Built at Shrewsbury When built 1833
 By whom built W B Bally Owners A Christate
 Port belonging to London Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock Bullhead Dock

Original Survey, No. _____ Dated January 1835 Clapd NA!
 Port London

Repairs. At the present time caulked from the
keel up and recoppered

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
 Spirketting _____
 Plank Shears _____
 Topsides _____
 Upper Deck with its Appendages _____
 Lower Deck Fastenings _____

Wales _____
 Counter _____
 Plank and Treenails _____
 (Outside to the Water's Edge.)
 Rudder _____
 Winlass _____
 Capstan _____

General Observations and Opinion, She appears to be firm and in good order,
 as required by the Instructions, throughout & entitled to remain in her present
Clap George Bayley

The Amount of Fee.....£ : : is received by me.

Committee Minute _____ 183 _____

Character assigned See annexed Survey No 5159