

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date March 24th 18 36
on the Ship Thomas King Master Williams
Tonnage 346 Built at London When built July 1826
By whom built Curling & Co Owners Wm King
Port belonging to London Destined Voyage America
If Surveyed Afloat or in Dry Dock Afloat Curling's Dry Dock

Original Survey, No. _____ Dated March 1835 Claford
Port London

Repairs. *At the present time in consequence of damage sustained on the voyage out - New Head, Knee, Ribs & Chocks -*

The Surveyor to state the present Condition of

Upper Deck Fastenings _____
Spirkettling _____
Plank Shears _____
Topsides _____
Upper Deck with its Appendages _____
Lower Deck Fastenings _____

Good

Wales _____
Counter _____
Plank and Treennails
(Outside to the Water's Edge) _____
Rudder _____
Windlass _____
Capstan _____

Good

General Observations and Opinion, *This vessel has not sustained any injury as required by the Instructions, other parts of the Hull - Her condition is very good throughout - Copper in good order. In my opinion she is fully entitled to 12A1*

George Bayley

The Amount of Fee..... £ : : is received by me.

Committee Minute _____ 183 _____

Character assigned See annexed Survey