

REPORT of SURVEY for REPAIRS.

No. _____ Port of London Date Sept 28 1835
 Survey of the Ship Thomas King Master Williamson
 Tonnage 346 By whom built Curling & Co Where built London
 When built July 1825 Owners Wm King Port belonging to London
 Destined Voyage Demerara
 Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. _____ Dated March 16. 1835
 Port London

Repairs. At the present time Copper repaired—

General Observations
and Opinion, as
required by the
Instructions

There is not any appearance of working or
 make up about this vessel in any part to which
 I have been able to obtain access. She has in addition
 to the usual Iron nail fastening a through bolt through
 every 4th Timber and clenched inside.

Her Masts, Rigging, Sails, Cables Anchors and
 Hawsers are all in good and efficient condition

George Bayley

The Amount of Fee.....£ : : is received by me.

Committee Minute _____ 183 _____

Character assigned See annexed Survey



© 2019

Lloyd's Register
Foundation

LON 605-0091