

REPORT of SURVEY for REPAIRS.

& Change of Property

Handwritten initials/signature

No. 117 Survey held at London Date May 8th 1839

on the SS Margaret Master J Honey

Tonnage 75 Built at Dundee When built 1829

By whom built _____ Owners Pittard & Co

Port belonging to Bristol Destined Voyage Coastways

If Surveyed Afloat or in Dry Dock on the Mays

Original Survey, No. 104 Dated _____ Classed 8 B.1

Port Aberdeen

Repairs At the present time Bottom Caulked

The Surveyor is also required to state the present Condition of the

| | | |
|-------------------------------|--|----------------------------|
| Decks | Transoms | Windlass |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Capstan |
| Lower Deck Beams & Fastenings | Topsides | Pumps |
| Spirkettling | Wales | Masts, Yards, Sc. |
| Plank Shears | Counter | Sails |
| Waterways | Plank and Treenails (Outside to the Water's Edge) | Cables |
| Hatchway Comings | Rudder | Anchors No. of |
| Breasthooks | Copper | Standing & Running Rigging |

General Observations and Opinion, Ship in very good condition for the safe conveyance
as required by the Instructions, Dry & perishable cargoes and may be stowed
A.1
W. Wilson

The Amount of Fee.....£ — : 10 : 6 is received by me, [Signature]

Committee Minute 14 May 1839

Character assigned A.1

