

REPORT of SURVEY for REPAIRS.

No. 105 Survey held at London Date May 11 18 39
on the Brig Harmony Master Taylor
Tonnage 231 Built at Yarmouth When built 1832
By whom built F. Preston Owners Latrobe
Port belonging to London Destined Voyage Labrador
If Surveyed Afloat or in Dry Dock at both ways

Original Survey, No. 1141, 2439 Dated 1836 Classed 11 A 1
Port London 2560, 5135,

Repairs

at the present time in consequence of decay - New Topside & Sheerstrakes from the after part of the Forehatch forward - several Top timbers shifted on each side and the defective parts removed - Caulked keel to water-tight -

The Surveyor is also required to state the present Condition of the

Decks	<u>Good</u>	Transoms		Windlass	
Upper Deck Beams & Fastenings	<u>"</u>	Timbers of the Frame	<u>Good</u>	Capstan	
Lower Deck Beams & Fastenings	<u>"</u>	Topsides		Pumps	
Spirketting	<u>"</u>	Wales		Masts, Yards, &c.	<u>Good & efficient</u>
Plank Shears	<u>"</u>	Counter		Sails	
Waterways	<u>"</u>	Plank and Treenails (Outside to the Water's Edge)		Cables	
Hatchway Comings	<u>"</u>	Rudder		Anchors No. of	
Breasthooks	<u>"</u>	Copper		Standing & Running Rigging	

General Observations and Opinion,
as required by the Instructions,

The Frame abaft the Fore Rigging was not in the slightest degree affected by the Dry Rot - She is now in my opinion in an efficient state of Repair and eligible to remain as classed 11 A 1

The Amount of Fee.....£ 1 : 1 : - is received by me,

Committee Minute 21 May 1839

Character assigned 11 A 1 repaired