

REPORT of SURVEY for REPAIRS.

No. 488 Survey held at London Date March 2nd 1839
 on the Schooner Hope Master J. Brier
 Tonnage 125 Built at Plymouth When built 1820
 By whom built _____ Owners Silwell & Co
 Port belonging to London Destined Voyage Rotterdam
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1828, 3342, Dated January 1839 NA
 Port of London 14789

Repairs. In consequence of damage has had six planks in the Starboard bow, four planks on the larboard bow regularly shifted & caulked

The Surveyor to state the present Condition of	
Upper Deck Fastenings _____	Wales _____
Spirkelling _____	Counter _____
Plank Shears _____	Plank and Treenails _____
Topsides _____	(Outside to the Water's Edge)
Upper Deck with its Appendages _____	Rudder & _____
Lower Deck Fastenings _____	Windlass _____
	Capstan _____

General Observations and Opinion, The timbers were exposed very sound & strong
 as required by the Instructions, if opinion may retain her present shape
W. M. Wilson

The Amount of Fee..... £ — : 10 : 6 is received by me. W. M. Wilson

Committee Minute 24 May 1839

Character assigned Fit for service
W. M. Wilson