

REPORT of SURVEY for REPAIRS.

No. 5363 Survey held at London Date June 14th 1839
on the Ship Atlas Master Hunt
Tonnage 412 Built at London When built 1820
By whom built _____ Owners Chalmers & Guthrie
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Hutchins Dry Dock

Original Survey, No. _____ Dated 1835 Classed A 1. return 6 years
Port London 1837

Repairs At the present time stripped caulked from keel up, thoroughly overhauled, Felled, woodsheathed and coppered to the wale ~~hull~~ keelson caulked - The long standing leak proved to be in the seam near the keel -

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>1839</u>	Standing & Running Rigging

General Observations and Opinion, This ship appears to be entitled to remain as classed A 1
as required by the Instructions, her general appearance being very favorable

George Bayley

The Amount of Fee.....£ : : is received by me,

Committee Minute 26 June 1839

Character assigned _____