

REPORT of SURVEY for REPAIRS.

5363

No. 882 Survey held at London Date 10 & 22 June 18 39
 on the Ship Atlas Master Hunt
 Tonnage 412 Built at London When built 1820
 By whom built - Owners Chalmers & Co.
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Hutchins Dock

Original Survey, No. 1618, 2647 Dated 34 21 Classed as per 1835 6.A.1
 Port London

Repairs *At the present time Shipped bottom covered sheetrock with wood, upper course fitted with paper below &opper to the holes.*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <i>overhauled</i>
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of <i>and good</i>
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

The look that she has hitherto had is now supposed to be stopped she appears throughout in an efficient condition & may be continued as before

The Amount of Fee.....£ 2 ; 2 : - is received by me, *HH*

Committee Minute 20 June 1839

Character assigned N.B.A. 1 revised repairs