

ANNUAL SURVEYS.

5371

No. 36 Survey held at London Date 8 June 1839
 on the Bullington Master Lindall
 Tonnage 473 Built at Bombay When built 1810
 By whom built — Owners Covent
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 2673, 3423 Port of London
4243

Classed F 171

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>Condition</u>	Topsides <u>Good</u>	Sails
Plank Shears	Wales <u>Condition</u>	Cables <u>Good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of <u>Condition</u>
Hatchway Comings	Rudder	Standing & Running Rigging <u>Sufficient</u>
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions, At the present time Wales stop could be
continued in good and efficient condition
fit for the conveyance of any and perishable cargo & may be
continued as before

Committee Minute 28 June 1839

Character assigned 1st Antient Continued

No. 3 Survey held at London Date 14 June 1839
 on the Ship Wakefield Master —
 Tonnage 607 Built at J. Johns St B When built 1832
 By whom built — Owners Harmon
 Port belonging to J. Johns Destined Voyage —
 If Surveyed Afloat or in Dry Dock Pickers Dock

Original Survey, No. 336, 1828 Port of Liverpool
2599

Classed —

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions, Had been a ground but sustained no damage
bottom could not yet opened, still in weak
of occasional fastenings

Committee Minute 28 June 1839

Character assigned Antient Continued