

REPORT of SURVEY for REPAIRS.

No. ⁴³ Survey held at LONDON Date June 26 1839
on the Bark Napoleon Master Joyce
Tonnage 233 Built at Jersey When built 1834
By whom built _____ Owners Ramin
Port belonging to Jersey Destined Voyage _____
If Surveyed Afloat or in Dry Dock Hatchers Dock

Original Survey, No. 3824/1182 Dated 1837 Classed 8A1
Port LONDON

Repairs at the present time stripped - 2 Planks shifted
in upper course Starboard Side - & 4 do on the Starboard
(of Dantzic oak) Caulked to Wale, Coppered to 14 feet
on Paper - Fore & Main Mast cut

The Frame appears to be in fair condition

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>1839</u>	Standing & Running Rigging

General Observations and Opinion,
as required by the Instructions,

In my opinion this ship is eligible to
remain as clasped 8A1

George Bentley

The Amount of Fee.....£ 1 : 1 : - is received by me, HA

Committee Minute 9th July 1839

Character assigned 8A1 Record Copper