


5457

S. 

Original Survey, No. 495,2723, Dated July 1838 Classed A.1
Port London 3540, 4297.

Repairs At the present time Shipped - the bottom of the original bottom cleared, examined and secured - Water doubled - 2 Short Planks Shifted Starboard Bow - Caulked from the Keel up and Sheathed with Yellow Metal to the Water - New Iron Channels - & generally overhauled


The Surveyor is also required to state the present Condition of the

Decks		Transoms		Windlass		
Upper Deck Beams & Fastenings	} Good	Timbers of the Frame	} Good	Capstan	} Good and efficient	
Lower Deck Beams & Fastenings		Topsides		Pumps		
Spircketting		Wales		Masts, Yards, &c.		
Plank Shears		Counter		Sails		} Good & efficient
Waterways		Plank & Treenails (Outside to the Water's Edge)		Cables		
Hatchway Comings	Rudder	Anchors	No. of	See		
Breasthooks	Copper	July 1839		Standing & Running Rigging	New Mast & Top Mast Revised	

*General Observations and Opinion,
as required by the Instructions,*

In my opinion the condition of this ship is such as to
warrant her to remain as at present chartered ^{N. A.}

George Bayley

The Amount of Fee.....£ 2 : 2 : — is received by me, 

Committee's Minutes 23 July 1839

Character assigned F.V. Asterisk Record Yellow Metal