

REPORT of SURVEY for REPAIRS.

No. 5468 Port of London Date Sept 7 1835
 Survey of the Ship Jamaica Master Johnson
 Tonnage 369 By whom built _____ Where built Bristol
 When built 1821 Owners Billinghurst Port belonging to London
 Destined Voyage Antigua
 Surveyed Afloat, or in Dry Dock Open Dock
See Survey for Damages Annexed

Original Survey, No. _____ Dated Sept 1834 Classed F.1
 Port London

Repairs. At the present time stopped - Caulked from the keel upwards - 3 Pair long diagonal Rides put in - 2 pair forward and 1 pair abaft - extending from the Lower Deck to the Floor Heads - Upper Course board sheathed and Felted - & Recoppered - The ship has been generally overhauled -

General Observations and Opinion, as required by the Instructions { The additional fastenings now put in, are in consequence of her having wrinkled her copper - which they are intended to prevent -
 The Bottom when exposed was found to be in good condition as were the keels. Topside Rudder, Decks, Deck fastenings, Waterways, Breast Hooks & Transoms - The ship should in my opinion remain classed F.1
George Bayley

The Amount of Fee.....£ : : is received by me.

Committee Minute _____ 183 _____

Character assigned See annexed Survey

Billinghurst St



© 2019

Lloyd's Register
Foundation

LON 605-0355