

REPORT of SURVEY for REPAIRS.

No. 5468 Survey held at London Date Oct^r 31 1835
 on the Ship Jamaica Master Simpson
 Tonnage 369 Built at Bristol When built 1821
 By whom built _____ Owners Billinghurst
 Port belonging to London Destined Voyage Antigua
 If Surveyed Afloat or in Dry Dock Afloat
See annexed Survey

Original Survey, No. _____ Dated 1834 Classed F. 1
 Port London

Repairs.

At the present time in consequence of damage—
 New Forecastle Deck Hook—Additional Hook over the
 Hawse Holes—New Knee of Head—Cheek—& Rails
 New Foremast Bowsprit. Iron and chain Bommets
 and Iron Rigging refitted—

General Observations and Opinion, as required by the Instructions

The damages received appear to be efficiently
 repaired—The stem has not received any
 apparent injury—The Larboard Knight Head
 appears to be twisted in a slight degree—
 Having been so recently reported (Sept^r 1835)
 condition of the
 there needs no observation as to the other
 parts of the ship. In my opinion she ought
 to remain classed F. 1
 George Bayley

The Amount of Fee.....£ : : is received by me.

Committee Minute _____ 183 _____

Character assigned See annexed Survey

By report in Sept^r 7th 1835
 Not Int^d