

ANNUAL SURVEYS.

5493

No. ³⁶¹ Survey held at London Date July 26th 1839
 on the B^g Britannia Master Young
 Tonnage 315 Built at Sunderland When built 1783
 By whom built _____ Owners T Sturge
 Port belonging to London Destined Voyage Other
 If Surveyed Afloat or in Dry Dock in Evans Dry Dock

Original Survey, No. 4323 Port of London 1030 Classed E, 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks <u>Sound</u>	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings <u>Fair</u>	Timbers of the Frame	Masts, Yards, &c.
Spirketting <u>condition</u>	Topsides <u>Fair</u>	Sails <u>Well</u>
Plank Shears	Wales <u>condition</u>	Cables <u>frank</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, At the present time sheathing stripped off the Bottom
 as required by the Instructions, & Caulked; I am of opinion is in good condition for
the safe conveyance of cargo not in their nature
subject to sea damage & may remain as placed

Committee Minute 2 August 1839

Character assigned F. A

No. 165 Survey held at London Date July 26th 1839
 on the B^g Hebe Master Douglas
 Tonnage 102 Built at Whitby When built 1827
 By whom built _____ Owners Douglas & Co
 Port belonging to London Destined Voyage Best vice
 If Surveyed Afloat or in Dry Dock on the ways

Original Survey, No. 1036^x 2806 Port of London 1037 Classed Continued A, 3 years
3852

The Surveyor is required to state the present Condition of the

Decks	Breasthooks <u>Sound</u>	Capstan
Upper Deck Beams & Fastenings	Transoms <u>"</u>	Pumps <u>good</u>
Lower Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>sound where seen</u>	Masts, Yards, &c. <u>"</u>
Spirketting	Topsides <u>good</u>	Sails <u>Well frayed</u>
Plank Shears	Wales <u>"</u>	Cables <u>"</u>
Waterways	Plank & Treenails (Outside to the Water's Edge) <u>"</u>	Anchors No. of <u>"</u>
Hatchway Comings	Rudder <u>"</u>	Standing & Running Rigging <u>good</u>
	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion, At the present time Copper patched & treenails
 as required by the Instructions, examined & caulked, is in good condition & may
continue as placed

Committee Minute 2 August 1839

Character assigned Cont. 3 A