

# ANNUAL SURVEYS.

5494

No. 554 Survey held at London Date July 31 1839  
 on the Brig Mary and Jane Master Walter  
 Tonnage 197 Built at Sunderland When built 1829  
 By whom built \_\_\_\_\_ Owners Walter  
 Port belonging to London Destined Voyage C. I. H.  
 If Surveyed Afloat or in Dry Dock at Newbarn Wharf

Original Survey, No. 2611, 4613 Port of London 1838 Classed Cont. 3A1  
 for 1838

The Surveyor is required to state the present Condition of the

|                               |   |                                     |
|-------------------------------|---|-------------------------------------|
| Decks                         | Breasthooks   | Capstan                             |
| Upper Deck Beams & Fastenings | Transoms  | Pumps                               |
| Lower Deck Beams & Fastenings | Timbers of the Frame                                  | Masts, Yards, &c.                   |
| Spirkettling                  | Topsides  | Sails                               |
| Plank Shears                  | Wales   | Cables                              |
| Waterways                     | Plank and Treenails<br>(Outside to the Water's Edge.) | Anchors No. of                      |
| Hatchway Comings              | Rudder  | Standing & Running Rigging          |
|                               | Windlass  | Copper <u>largely repaired 1839</u> |

General Observations and Opinion, At the present time caulked from the Copper up, and then  
 as required by the Instructions, Copper largely repaired - One plank of Sheer shifted on  
the Starboard side amidships (Timber good) - Her general  
appearance is fair & good & in my opinion is in an efficient  
state to remain as classed A 1

Committee Minute 2 August 1839

Character assigned Cont. 3 A1

No. 476 Survey held at London Date July 31 1839  
 on the Brig Lusitania Master Gibbons  
 Tonnage 275 Built at Yarmouth When built 1821  
 By whom built Doel Owners Gibbons  
 Port belonging to Yarmouth Destined Voyage Spain  
 If Surveyed Afloat or in Dry Dock Newbarn Dry Dock

Original Survey, No. 2982, 3370 Port of London 1837 Classed A 1

The Surveyor is required to state the present Condition of the

|                               |   |                            |
|-------------------------------|---|----------------------------|
| Decks                         | Breasthooks   | Capstan                    |
| Upper Deck Beams & Fastenings | Transoms  | Pumps                      |
| Lower Deck Beams & Fastenings | Timbers of the Frame                                  | Masts, Yards, &c.          |
| Spirkettling                  | Topsides  | Sails                      |
| Plank Shears                  | Wales   | Cables                     |
| Waterways                     | Plank and Treenails<br>(Outside to the Water's Edge.) | Anchors No. of             |
| Hatchway Comings              | Rudder  | Standing & Running Rigging |
|                               | Windlass  | Copper <u>single</u>       |

General Observations and Opinion, at the present time retaining from the light masts  
 as required by the Instructions, downwards to the Bilge & caulking - shifting the Channels  
& some planks of upperworks - She is in my opinion slightly  
the present class B 1

Committee Minute 2 August 1839

Character assigned B 1



© 2019

Lloyd's Register  
Foundation



July 31

4 Repairs

2 Annual

3 Special Surveys

9

1 Average Papers

10



© 2019

Lloyd's Register  
Foundation